



# KEI16 - SERVICE RECORD LOG

Vehicle Rego Number: XQ98EC From: \_\_\_\_\_ To: \_\_\_\_\_ Page: \_\_\_\_\_

Date	Odometer	Type of Service A,B,C,D	Repair Details	Service/Repairs Carried Out By	Next Service Due
27.12.18	3441 km / 140 h	A		Madill ISUZU	within 5000 km
08.08.19	7232 km / 392 h	A		Keilyn Pty Ltd	
09.12.19	975 h	B		CPE Concrete Pump Engineering	
06.08.20	12974 km	A		Keilyn Pty Ltd	
30.02.21	20079 km	B		" " "	
15.06.21	26,014 km	A		" " "	
28.09.21	32,350 km	A		" " "	
28.01.22	36,540 km	A		" " "	
14.06.22	40416 km	B		" " "	
23.09.22			Repair air leak, repair air dryer	Madill ISUZU	